


Subject: Sample Energy Manager Report
Attachments: Selma Summary.csv; Backup 1(460).csv; Backup 2(464).csv; Building 75A(458).csv; Building 75B(461).csv; Building 76(459).csv; Building 78(462).csv; Building 79(463).csv; Building 80(456).csv; Building 81(457).csv; Building 82(450).csv; Building 83(452).csv; Building 84(453).csv; Building Red(455).csv; Building Sign(451).csv; Parking Lot(454).csv


Energy Usage Report

Selma

From: May 05, 2011 17:27
To: May 06, 2011 17:27

Selma Energy Usage





Circuit	Usage	% of Total
Backup 1	0.000 kWh	0.00%
Backup 2	0.000 kWh	0.00%
Building 75A	41.997 kWh	3.08%
Building 75B	15.017 kWh	1.10%
Building 76	29.153 kWh	2.13%
Building 78	0.000 kWh	0.00%
Building 79	20.036 kWh	1.47%
Building 80	4.320 kWh	0.32%
Building 81	6.092 kWh	0.45%
Building 82	850.359 kWh	62.26%
Building 83	237.535 kWh	17.39%
Building 84	82.494 kWh	6.04%
Building Red	21.970 kWh	1.61%
Building Sign	25.860 kWh	1.89%
Parking Lot	30.915 kWh	2.26%
Total	1365.748 kWh	100%